


AIRPROX REPORT No 2016181

Date: 24 Aug 2016 Time: 1435Z Position: 5324N 00034W Location: N of Scampton

PART A: SUMMARY OF INFORMATION REPORTED TO UKAB

Recorded	Aircraft 1	Aircraft 2
Aircraft	Tornado GR4	Glider
Operator	HQ Air (Ops)	Unknown
Airspace	Lon FIR	
Class	G	
Rules	VFR	
Service	None	
Provider	NA	
Altitude/FL	FL004	
Transponder	A, C, S	
Reported		
Colours	Grey	White
Lighting	NK	
Conditions	VMC	
Visibility	>10km	
Altitude/FL	250-350ft AGL	
Altimeter	RPS (1012hPa)	
Heading	270°	
Speed	420kt	
ACAS/TAS	TCAS II	
Alert	None	
Separation		
Reported	0ft V/80m H	
Recorded		NK



THE TORNADO PILOT reports that he was conducting a low-flying portion of a sortie, which had been planned, input into CADS and low-level bookings made. Whilst flying west through the Scampton/Kirton-in-Lindsey gap, the pilot saw a light aircraft, believed to be a glider, flying in the opposite direction. It appeared to be co-altitude, approximately 70-100m offset, and banking away. When spotted, it was already in the 2:30 position and too late to take any avoiding action. The crew were listening out on the low-level common frequency at the time, although were in the process of trying to raise Waddington ATC to ask for an ATS from them.

He assessed the risk of collision as ‘Low’.

The glider pilot could not be traced.

Factual Background

The weather at Scampton was recorded as follows:

METAR EGXP 241450Z 07009KT 9999 FEW034 25/16 Q1019 BLU=

Analysis and Investigation

UKAB Secretariat

The Tornado and glider pilots shared an equal responsibility for collision avoidance and not to operate in such proximity to other aircraft as to create a collision hazard¹. If the incident geometry

¹ SERA.3205 Proximity.

is considered as head-on or nearly so then both pilots were required to turn to the right². If the incident geometry is considered as converging then the Tornado pilot was required to give way to the glider³.

Comments

HQ Air Command

The Tornado crew had planned their mission in accordance with all extant procedures, including submission of the low-level routing onto CADS. The TCAS II fitted to the Tornado was set to 'TA' mode and, whilst there were indications of other contacts, the Airprox aircraft was not apparent on the Tornado's TCAS display. The crew were flying at 250-350ft AGL and were monitoring the low-level common frequency which, in this part of the UK, is a UHF frequency and therefore is unlikely to be monitored by anything other than military aircraft; the crew was also in the process of raising Waddington ATC with a view to agreeing an Air Traffic Service. Therefore, and in the assumption that the other aircraft was not carrying any form of electronic conspicuity (due to lack of TCAS contact and no SSR return apparent), the only viable barrier to MAC in this instance was 'see-and-avoid'. The Tornado crew spotted the other aircraft with insufficient time to materially affect the separation, but the other aircraft was seen to be banking away so may well have seen the approaching Tornado and taken avoiding action. This encounter once again highlights the indispensability of disciplined lookout in the detection and avoidance of other air systems.

Summary

An Airprox was reported when a Tornado and a glider flew into proximity at 1435 on Wednesday 24th August 2016. The Tornado pilots was operating under VFR in VMC and not in receipt of an ATS. The glider pilot could not be traced.

PART B: SUMMARY OF THE BOARD'S DISCUSSIONS

Information available consisted of reports from the Tornado pilot, radar photographs/video recordings, and a report appropriate operating authorities.

The Board first looked at the actions of the Tornado pilot; he had planned his sortie, entered it into CADS and was conducting his low-level routing in accordance with all of the relevant regulations. Members noted that he had reported that the other aircraft was approximately the same height as he was, and the Board thought that 300ft was very low for a glider, even if it was trying to return to Kirton-in-Lindsey, although it could have been a motor-glider who was starting his engine. The glider member commented that, without power or a fortuitous thermal, a glider wouldn't have made it back to Kirton-on-Lindsey at that height. Other members commented that the aircraft was also quite low for a light aircraft, and some members even opined that it could have been a model, closer than the Tornado pilot perceived. In truth they just didn't know. The Board noted that, without a transponder, whatever it was wouldn't give any indications on the Tornado's TCAS and, even if the Tornado pilot had been receiving an ATS from Waddington, it wouldn't show on their radar anyway. This left lookout as the final mitigation against mid-air collision; although the Tornado pilot had seen the other aircraft late, the Board noted that he described it as banking away, and they wondered whether in fact the other pilot had seen the Tornado and was manoeuvring to avoid it.

In assessing the effectiveness of the safety barriers associated with this incident, the Board concluded that the key factors had been that:

² SERA.3210 Right-of-way (c)(1) Approaching head-on.

³ SERA.3210 Right-of-way (c)(2) Converging.

- **Situational Awareness** and **See-and-Avoid** had both only been **partially effective**; the Tornado pilot had not been aware of or seen the glider until he had effectively passed it.
- **Onboard Warning/Collision Avoidance Equipment** had been **ineffective**; the lack of transponder signals from the glider/aircraft had meant that the Tornado TCAS could not provide warnings.

Turning to the cause, given the lack of information from the glider pilot regarding whether he had seen the Tornado, and the fact that the glider would have been a difficult object to see any earlier head-on, at high-speed at low-level, the Board thought that the best way to describe the situation was as a conflict in Class G airspace. Noting that the Tornado pilot saw the other aircraft too late to take avoiding action, some members thought that the risk category was fairly high given that he reported the separation as only 80m. Others thought that the risk might be less than this if the other pilot had already seen and manoeuvred to avoid the Tornado. In the end, the Board felt that there was not enough evidence to make a proper judgement on the risk, and therefore reluctantly recorded the risk as Category D; not enough information to assess.

The Board noted that the low-level frequency the Tornado pilot was listening out on was a UHF frequency and as such was unlikely to have been available to most GA traffic. In this respect, and following on from a previous trial in Scotland, members were heartened that the RAF Safety Centre was currently trying to secure a VHF common frequency in England/Wales for all to use; however, it was impossible to say whether the availability of such a frequency would have prevented this Airprox.

PART C: ASSESSMENT OF CAUSE AND RISK


Cause: A conflict in Class G airspace.

Degree of Risk: D.

Barrier assessment:

Modern safety management processes employ the concept of safety barriers that prevent contributory factors or human errors from developing into accidents. Based on work by EASA, CAA, MAA and UKAB, the following table depicts the barriers associated with preventing mid-air-collisions. The length of each bar represents the barrier's weighting or importance (out of a total of 100%) for the type of airspace in which the Airprox occurred (i.e. Controlled Airspace or Uncontrolled Airspace).⁴ The colour of each bar represents the Board's assessment of the effectiveness of the associated barrier in this incident (either Fully Effective, Partially Effective, Ineffective, or Unassessed/Inapplicable). The chart thus illustrates which barriers were effective and how important they were in contributing to collision avoidance in this incident.

⁴ Barrier weighting is subjective and is based on the judgement of a subject matter expert panel of aviators and air traffic controllers who conducted a workshop for the UKAB and CAA on barrier weighting in each designation of airspace.



Barrier Effectiveness		Consequence		
		Non-functional	Partially Functional	Functional
Availability		1	2	3
Completely Unavailable	1	1	2	3
Partially Available	2	2	4	6
Available	3	3	6	9

Key:

- Effective
- Partially Effective (If the system was partially available but fully functional score availability as 2.5)
- Ineffective
- Unassessed/Inapplicable

Barrier	Availability			Functionality			Unassessable / Absent
	Fully (3)	Partially (2)	Not Available (1)	Fully (3)	Partially (2)	Non Functional (1)	
Airspace Design and Procedures	Appropriate airspace design and/or procedures were available	Airspace design and/or procedures were lacking in some respects	Airspace design and/or procedures were not appropriate	Airspace design and procedures functioned as intended	Airspace design and/or procedures did not function as intended in some respects	Airspace design and/or procedures did not function as intended	The Board either did not have sufficient information to assess the barrier or the barrier did not apply; e.g. TCAS not fitted to either aircraft or ATC Service not utilised. Note: The Board may comment on the benefits of this barrier if it had been available
ATC Strategic Management and Planning	ATM were able to man and forward plan to fully anticipate the specific scenario	ATM were only able to man or forward plan on a generic basis	ATM were not realistically able to man for or anticipate the scenario	ATM planning and manning functioned as intended	ATM planning and manning resulted in a reduction in overall capacity (e.g. bandboxed sectors during peak times)	ATM planning and manning were not effective	
ATC Conflict Detection and Resolution	ATS had fully serviceable equipment to provide full capability	ATS had a reduction in serviceable equipment that resulted in a minor loss of capability	ATS had a reduction in serviceable equipment that resulted in a major loss of capability	The controller recognised and dealt with the conflict in a timely and effective manner	The controller recognised the conflict but only partially resolved the situation	The controller was not aware of the conflict or his actions did not resolve the situation	
Ground-Based Safety Nets (STCA)	Appropriate electronic warning systems were available	Electronic warning systems is not optimally configured (e.g. too few/many alerts)	No electronic warning systems were available	Electronic warning systems functioned as intended, including outside alerting parameters, and actions were appropriate	Electronic warning systems functioned as intended but actions were not optimal	Electronic warning systems did not function as intended or information was not acted upon	
Flight Crew Pre-Flight Planning	Appropriate pre-flight operational management and planning facilities were deemed available	Limited or rudimentary pre-flight operational management and planning facilities were deemed available	Pre-flight operational management and planning facilities were not deemed available	Pre-flight preparation and planning were deemed comprehensive and appropriate	Pre-flight preparation and/or planning were deemed lacking in some respects	Pre-flight preparation and/or planning were deemed either absent or inadequate	
Flight Crew Compliance with Instructions	Specific instructions and/or procedures pertinent to the scenario were fully available	Instructions and/or procedures pertinent to the scenario were only partially available or were generic only	Instructions and/or procedures pertinent to the scenario were not available	Flight crew complied fully with ATC instructions and procedures in a timely and effective manner	Flight crew complied later than desirable or partially with ATC instructions and/or procedures	Flight crew did not comply with ATC instructions and/or procedures	
Flight Crew Situational Awareness	Specific situational awareness from either external or onboard systems was available	Only generic situational awareness was available to the Flight Crew	No systems were present to provide the Flight Crew with situational awareness relevant to the scenario	Flight Crew had appropriate awareness of specific aircraft and/or airspace in their vicinity	Flight Crew had awareness of general aircraft and/or airspace in their vicinity	Flight Crew were unaware of aircraft and/or airspace in their vicinity	
Onboard Warning/Collision Avoidance Equipment	Both aircraft were equipped with ACAS/TAS systems that were selected and serviceable	One aircraft was equipped with ACAS/TAS that was selected and serviceable and able to detect the other aircraft	One aircraft was equipped with ACAS/TAS that was selected and serviceable but unable to detect the other aircraft (e.g. other aircraft not transponding)	Equipment functioned correctly and at least one Flight Crew acted appropriately in a timely and effective manner	ACAS/TAS alerted late/ambiguously or Flight Crew delayed acting until closer than desirable	ACAS/TAS did not alert as expected, or Flight Crew did not act appropriately or at all	
See and Avoid	Both pilots were able to see the other aircraft (e.g. both clear of cloud)	One pilots visibility was uninhibited, one pilots visibility was impaired (e.g. one in cloud one clear of cloud)	Both aircraft were unable to see the other aircraft (e.g. both in cloud)	At least one pilot takes timely action/inaction	Both pilots or one pilot sees the other late and one or both are only able to take emergency avoiding action	Neither pilot sees each other in time to take action that materially affects the outcome (i.e. the non-sighting scenario)	